



PrintLog3D.com
MATERIALS. SETTINGS. LOGS. RESULTS.

FREE PRINTABLE FIELD GUIDE

FILAMENT SETTINGS FIELD GUIDE

31 MATERIALS. ONE REFERENCE. LESS GUESSWORK.

Start with the published range, record what actually works on your machine, and build a repeatable settings history instead of printing from memory.



USE THE GUIDE LIKE A DATA LOOP

01

CHOOSE

Find your material and start inside the published range.

02

PREP

Meet the enclosure, cooling, and drying notes before tuning.

03

PRINT

Run a controlled test on your actual printer and filament.

04

LOG

Write down the settings and the result - good or bad.

05

TUNE

Change deliberately, then keep the setting that earned the result.

STARTING POINTS, NOT MAGIC NUMBERS

These are typical manufacturer-published ranges - not measurements taken by PrintLog3D. Always check your filament maker's own figures.

LIVE MATERIAL LIBRARY

Guides, material pages, updates

[PRINTLOG3D.COM](https://printlog3d.com)



PRACTICAL SETTINGS. REAL RESULTS. NO MORE PRINTING FROM MEMORY.



31-MATERIAL SETTINGS MATRIX

Typical published ranges at a glance. Use the material maker as the final authority.

NO ENCLOSURE

ENCLOSURE REQUIRED

DRYING GUIDANCE

MATERIAL	NOZZLE C	BED C	ENCLOSURE	PART COOLING	DRY AT
PLA	180-220	50-60	Not needed	Yes (100%)	45C / 4-6h (opt.)
PETG	220-250	70-85	Not needed	Yes (30-50%)	65C / 4-6h
ABS	220-250	100-110	REQUIRED	No / low	65-80C / 2-4h
ASA	235-255	90-110	REQUIRED	No / low	70-80C / 4h
PC	260-310	100-120	REQUIRED	No	80C / 6-8h
PEEK	370-420	120-160	REQUIRED	No	120-150C / 3h
Nylon PA6	230-260	70-90	REQUIRED	Minimal	70-80C / 8-12h
Nylon PA12	240-270	70-90	REQUIRED	Minimal	70-80C / 8-12h
PA-CF	260-280	80-100	REQUIRED	Minimal	70-80C / 8-12h
PETG-CF	240-260	80-90	Not needed	Yes (30-50%)	65C / 4-6h
PCTG	230-250	70-85	Not needed	Yes (30-50%)	65C / 4-6h
CPE	240-260	75-90	RECOMMENDED	Yes	65-70C / 4-6h
HIPS	220-250	100-115	REQUIRED	No / low	65C / 4h (opt.)
PLA Silk	195-225	50-60	Not needed	Yes (50-70%)	45C / 4-6h (opt.)
PLA Matte	195-220	50-60	Not needed	Yes (100%)	45C / 4-6h (opt.)
PLA Wood	190-220	50-60	Not needed	Yes	45C / 4-6h (opt.)
PLA Metal	190-225	50-60	Not needed	Yes	45C / 4-6h (opt.)

● A FILAMENT DRYER CANNOT DO THESE: PEEK

Domestic dryers stop near 90C. These need a high-temperature oven with a thermostat you have verified.



IMPORTANT: RANGE DOES NOT MEAN "BEST SETTING"

Printer geometry, filament brand, moisture, part design, and environment can change the useful setting. Use this matrix to choose a safe starting range, then log the result on your own machine.



SETTINGS MATRIX, CONTINUED

Flexibles, supports, composites and the high-temperature engineering grades.

NO ENCLOSURE

ENCLOSURE REQUIRED

DRYING GUIDANCE

MATERIAL	NOZZLE C	BED C	ENCLOSURE	PART COOLING	DRY AT
TPU	220-250	30-50	Not needed	Yes	50C / 4-6h
TPE	210-240	30-50	Not needed	Yes	45-50C / 4-6h
PVA	190-220	45-60	Not needed	Yes	45C / 6-8h
PP	220-250	85-100	RECOMMENDED	Yes	60-70C / 4h (opt.)
PVB	215-235	60-75	Not needed	Yes	50C / 4-6h
PLA-CF	190-230	50-60	Not needed	Yes	45-55C / 4-6h (opt.)
PA-GF	250-280	80-100	REQUIRED	Minimal	70-80C / 8-12h
ASA-CF	240-270	90-110	REQUIRED	No / low	70-80C / 4h
PC-CF	260-300	100-120	REQUIRED	No / low	80C / 6-8h
PEI (ULTEM)	370-410	140-180	REQUIRED	No	120-150C / several h
PPS	300-340	120-150	REQUIRED	No	100-120C / several h
Conductive PLA	195-220	50-60	Not needed	Yes	45C / 4-6h (opt.)
Glow PLA	200-225	50-60	Not needed	Yes	45C / 4-6h (opt.)
Magnetic PLA	195-225	50-60	Not needed	Yes	45C / 4-6h (opt.)

● A FILAMENT DRYER CANNOT DO THESE: PEI, PPS

Domestic dryers stop near 90C. These need a high-temperature oven with a thermostat you have verified.



IMPORTANT: RANGE DOES NOT MEAN "BEST SETTING"

Printer geometry, filament brand, moisture, part design, and environment can change the useful setting. Use this matrix to choose a safe starting range, then log the result on your own machine.



FAILURE MODES: THE FIRST THING TO CHECK

The most common problem called out for each material in the source guide - tightened into field-note format.

PLA**HEAT SOFTENING**

Parts soften around 60C. If the part must survive heat, move to PETG or ABS instead of trying to tune PLA.

PETG-CF**WRONG EXPECTATION**

Carbon fiber makes the material stiffer, not stronger in every sense. Impact resistance goes down, not up.

PETG**STRINGING**

Lower nozzle temperature 5C at a time and raise travel speed before changing retraction distance.

PCTG**AVAILABILITY**

The problem may be sourcing more than printing. Fewer brands carry it, so color choice is narrower than PETG.

ABS**WARPING / LAYER SPLIT**

Corners lift and layers split when the print is exposed to drafts. Enclose the printer and turn part cooling off.

CPE**NAME CONFUSION**

In 3D printing, CPE means co-polyester. Do not confuse it with chlorinated polyethylene, an unrelated industrial rubber.

ASA**WARPING + ODOR**

Similar warping behavior to ABS, with a stronger smell. Ventilate the room and keep the chamber warm and still.

HIPS**SUPPORT ASSUMPTIONS**

Do not buy it as support material unless you have a second extruder. On a single-nozzle printer it is simply an ABS-like filament.

PC**LAYER DELAMINATION**

A clean-looking print can still delaminate under load when the filament is wet. Dry it and keep it dry during printing.

PLA Silk**LOST SHEEN**

Too much cooling dulls the sheen. Reduce fan, print a little hotter, and slow down versus plain PLA.

PEEK**MACHINE LIMITS**

The main problem is often machine capability. If your hot end or bed cannot reach the required temperatures, tuning cannot solve it.

PLA Matte**ABRASIVE FILLER**

The matting filler is mildly abrasive. Brass can work, but expect faster nozzle wear than plain PLA.

Nylon PA6**MOISTURE**

Steam pops and a furry surface mean the filament is wet. Dry once is not enough - it needs to stay dry during the print.

PLA Wood**CLOGGING**

Wood particles bridge small nozzles easily. Use 0.4mm or larger and avoid long retractions.

Nylon PA12**BED ADHESION**

Nylon does not like a PEI build surface. A garolite or PA-specific sheet, or a glue-stick layer, can solve what temperature tuning will not.

PLA Metal**STRENGTH MYTH**

Metal filler adds weight and finish, but reduces strength compared with plain PLA.

PA-CF**NOZZLE WEAR**

Underextrusion that worsens over time can mean the carbon fiber has widened the nozzle bore. Use hardened steel or ruby before the first print.

TPU**FEED BUCKLING**

The filament buckles between the drive gear and the hot end instead of feeding. Slow to 15-25 mm/s and use direct drive.

THE GOAL IS NOT TO MEMORIZE FIXES. BUILD A REPEATABLE HISTORY.

Record the setting, the failure, the change, and the result on the print log.

[PRINTLOG3D.COM](https://printlog3d.com)



FAILURE MODES, CONTINUED

Flexibles, supports, composites and the high-temperature grades.

TPE**SOFTER, SOONER**

Everything that goes wrong with TPU goes wrong sooner. Direct drive is effectively mandatory and 15 mm/s is a sensible ceiling.

PC-CF**TOUGHNESS TRADED AWAY**

The carbon fibre removes much of polycarbonate's impact toughness and keeps all its difficulty. For drops, plain PC is better.

PVA**ARRIVES WET**

It degrades in the hot end on long prints because it absorbed water on the spool. Store it sealed from the day it arrives.

PEI (ULTEM)**CHAMBER, NOT BED**

A heated bed is not a heated chamber. Large parts delaminate partway up unless the chamber holds 120-180C.

PP**IT WILL NOT STICK**

PP bonds to itself and to very little else. Packing tape or a PP-specific sheet is the answer; bed temperature alone is not.

PPS**CRYSTALLISATION SHRINKAGE**

The part comes off the plate dimensionally different from the model. The fix is chamber temperature and part design, not slicer settings.

PVB**CLOUDING**

It takes on moisture noticeably faster than PLA, and a spool left out for a fortnight prints cloudy rather than clear.

Conductive PLA**NOT A WIRE**

Resistance rises with trace length, so a circuit working across 20mm fails across 200mm. Never put it near mains voltage.

PLA-CF**STIFFER, NOT STRONGER**

PLA-CF snaps where plain PLA would bend. Stiffness is the reason to choose it, not strength.

Glow PLA**PHOSPHOR IS ABRASIVE**

The phosphor is a hard mineral and eats brass faster than most carbon fills. Fit hardened steel first.

PA-GF**WORSE THAN CARBON**

Glass fibre is more abrasive than carbon, not less. Hardened steel is the minimum; ruby or tungsten if you print it often.

Magnetic PLA**FERROMAGNETIC, NOT MAGNETISED**

A printed part sticks to a magnet but holds nothing up by itself. It also genuinely rusts, so seal it if you do not want that.

ASA-CF**BOTH PROBLEMS AT ONCE**

It warps like ASA and wears nozzles like a composite. Enclose the printer and fit a hardened nozzle before the first print.

THE GOAL IS NOT TO MEMORIZE FIXES. BUILD A REPEATABLE HISTORY.

Record the setting, the failure, the change, and the result on the print log.

[PRINTLOG3D.COM](https://printlog3d.com)



LOG IT. LEARN IT. PRINT BETTER.

A clean record turns one good print into a repeatable process - and one failed print into useful evidence.

PRINT LOG - ONE RUN

MATERIAL + SETTINGS + RESULT

MATERIAL

e.g. PETG

BRAND / SPOOL

brand, color, batch

PRINTER

machine / profile

NOZZLE

diameter + material

NOZZLE

_____ C

BED

_____ C

FAN

_____ %

SPEED

_____ mm/s

PREP

☐ ENCLOSURE

☐ DRIED

☐ COOLING

RESULT

☒ CLEAN

☐ USABLE

☐ FAIL

WHAT HAPPENED?

NEXT CHANGE - ONE THING ONLY

FIELD REMINDERS

Pulled directly from the material notes.

PLA Heat sensitive near 60C.

ABS / ASA Control drafts; enclosure matters.

NYLON Keep it dry while printing.

PA-CF Use a hardened or ruby nozzle.

PEEK Machine capability is the gate.

PLA WOOD Use 0.4mm or larger nozzle.

PETG-CF Stiffer does not mean tougher.

KEEP THE LIVE REFERENCE HANDY



Scan for the material library
[PRINTLOG3D.COM](https://printlog3d.com)

31 MATERIALS ONE SETTINGS REFERENCE



Free to browse. Built to log.

PRACTICAL SETTINGS. REAL RESULTS.